

MB1500SE Upgrade Checklist

One of the bestselling ATM Machines to hit America was the MB1500. However, being over a decade old, some machines require more components to make it EMV Ready.

REQUIRED FOR EVERYONE:

- 1) 1500SE EMV UPGRADE KIT

REQUIRED FOR SOME:

- 2) **KEYPAD:** If the machine has a rubber keypad you need to upgrade the keypad and machine
 - New Version 4 Keypad
 - Upper Bezel
 - Keypad Mounting Bracket
 - Keypad Support Bracket

- 3) **PRINTER:** If the firmware version of the printer is V00.02.00 up through V00.03.05, a firmware upgrade to V00.03.07 will be required for the printer to correctly print receipts. In order to do the firmware, upgrade we need to send in the whole printer in to Hyosung so that it can be flashed. **Turn around is about 2 weeks. NOTICE: IF YOUR PRINTER BOARD PART NUMBER IS 723356-01 IT CANNOT BE REFLASHED. IT MUST BE REPLACED.**

S/W VERSION	
=====	
TODAY: 11/04/2014 07:44:51	
CANADA, NH-1500, MONO	

BIOS	: V21.21.05
APPLICATION	: V21.21.21
RMS	: V05.01.00

SPR ROM	: V00.02.00
CDU ROM(A10)32	: V00.01.04
EPP ROM	: V03.02.01
< SEGMENT CHECK SUM >	

BIOS : 0E48	SYSTEM : 4C8C
APPL : 8C15	TABLE : 1E86

S/W VERSION	
=====	
TODAY: 11/04/2014 07:44:51	
CANADA, NH-1500, MONO	

BIOS	: V21.21.05
APPLICATION	: V21.21.21
RMS	: V05.01.00

SPR ROM	: V00.03.05
CDU ROM(A10)32	: V00.01.04
EPP ROM	: V03.02.01
< SEGMENT CHECK SUM >	

BIOS : 0E48	SYSTEM : 4C8C
APPL : 8C15	TABLE : 1E86

If the S/W Version print-out shows a firmware version of V00.03.07, or V00.05.XX or higher, no firmware upgrade is required.

- 4) **DISPENSER:** A few MB1500s were shipped out with a TCDU dispenser. This dispenser is not compatible and must be replaced. If you see a black top reject cover, you have a TCDU.

If you need to replace 3 or more of the requirements, we recommend purchasing a new ATM.